

RLCEIVED MEMORANDUM

DATE:

TO:

January 5, 1983

Land Division File

E.P.A. - U.L.P.C. STATE OF ILLINOIS

MAR 16 1983

FROM:

Gerald E. Steele, DLPC/FOS-Central Region and

THE PLANT WAS A PROPERTY OF THE STATE SUBJECT: LPC

> An inspection of the Buerkett 31st Street Landfill was conducted on January 5, 1983, by this author. Ms. Barbara Ballard from the headquarter's office accompanied me. I spoke with Mr. Willie Buerkett at the conclusion of the inspection.

Pits A and B are still in need of additional final cover. No work is apparent on the south slope of pit A, hence, continuing the final cover violation. Refuse was observed protruding through available cover in the central level area and south central slope of pit B. Leachate was observed flowing through a break in the berm and ponding at the south edge of the berm to pit B. This was within the stream's floodplain.

Leachate was also seen in the west central part of pit C. It flowed from this location to a pond in the northwest part of the pit. A pond of black odorous leachate was observed in the northeast part of pit C. A break in the berm was observed at the location of this pond. The "sump" used for runoff water was located just south of this leachate. The sump accepts drainage from most of the pit. Water in the sump was slightly discolored black, and a minor garbage odor was detected. It appeared that only a few inches of elevation separated the sump water from the leachate, and the leachate from the breech in the berm.

Additional hardfill and some demolition waste has been placed on and beside the pad which was constructed at the entrance to pit C. Some of the waste has been deposited in the stream channel. Wood, metal, and a small amount of foam were seen mixed with hardfill along the edges. Waste had been deposited in piles at the end of the pad making it unusable until the piles were leveled. A permit violation for refuse being placed closer to the stream than fifty (50) feet was charged. Another break in the berm was seen just west of this location.

The site has begun accepting flyash from Commonwealth Edison at Kincaid. This waste was recently reclassified from a special waste to general refuse. The flyash is being deposited

> EPA Region 5 Records Ctr. 298766

LPC #16782516 - Sangamon County Springfield/Buerkett #2 (31st Street)

in the ditch between the fence and the filled part of pit C. This may be located off of the permitted boundary. An unpermitted entrance/exit has been constructed in the southeast corner of pit C onto Dirksen Parkway. This was done by separating the chain link fence at a post, rolling up two sections, and removing the post in the middle. Mr. Buerkett said this was done to allow easy and quick exit for the trucks hauling flyash. He said there was no gate present. The permit also calls for over 600 feet of paved roadway to minimize mud and debris tracked onto public roads. This is not available from the area where flyash is dumped to the exit in the corner of the pit.

The active area is located in the north central part of the site. Refuse was observed protruding through available cover over the approximate eastern ½ of the pit. The eastern ¼ needs one foot of intermediate cover, with the remaining filled area of C, including a strip along the south levee, needing additional daily cover. Large amounts of windblown litter, with some of it heavily weathered, was observed in the litter fences, site boundaries, and caught in vegetation in the stream channel. Flyash was being dumped from the top of the slope, with a nearly vertical working face.

GES/cp

cc: DLPC/FOS, Central Region Land Enforcement Programs

, .	INS	PECTION REPORT	(1) T - SITE INVE	(8)(9) ENTORY NO.	167825	16		
Sanga	m Oh	Co L.P.C.	. Region	ا) _ ر	1)	*(18)	e 09	70985
<i></i>	Scield	/ Black	1 4 0	(19)	   ott	er Sent (Ye	(20)	(25
(Locatio	oh)	(Respons	ible Party)	-		0	_	(26)
Samples Taken Ground Water(		No (XX). Tir e() Other (	me: From //	) : 15 1 m	Weath	ner Yartia	Uy Dun	my 879
Photos Taken:		No ( ) Int	4- 6	PACE BU	ER KETT Inspe	ector 1	<u> 4 /2</u>	<u></u>
Previous Inspe		78-85 Pre	evious Corres	spondence/	-15-0per	ating: Yes DRIZATION:	NO NO	( )
Operating	<u> ₩</u>	Sanitary La		Storage (		A. Permit	X	
Temporarily C	losed ( )	Random Dump	o ( )	Salvage (	) Varia		( )	
Closed Not Co		Other	( )	A.C.D. (	) 21 (	1.57	( )	
Closed and Co	vered ( )	Quantity Re	eceived Daily	<del></del>	<del></del>	d Order	( )	
				(	30) Appa		<i>(</i> -)	
			SITE EVAL	HATLON	Non-	Compliance	(5)	721
Leachate:	Ponded. on	site (X)						(31)
Leachate.	Flowing	n site $(X)$						33
		x)						34
		of past flows						35
	Observed	garbage ( ) ı	refuse ( ) in	n standing	water (X) .			36
	Flow ente	ring surface v	water (5)					37
		ing site (1 <b>-</b> 3)						38
Board Order:	0 10	violation obse						39
Court Order:		violation obse					11:1	40
Permit:	Additiona	ent viol <mark>ation</mark> l apparent vio	$\sigma_{1}$	- /	Approx &		etal	41 5
Daily Cover:		ded on previou					1011 101 01	43
		ded on previou						44
		e depth over a						45
		e depth over						46
		adequate depth						47 48
rinal cover:	Inadequat	e depth 1-3 ac e depth 3 or m	more acres (			* * * * *	101 10 10	The second second
	None 60 d	ays after area	a closure (5)	1				50
Unloading no	t supervis	ed(3)	a closure (),	/· · · · ·				51
		t toe of slope						
Inadequate s	preading a	nd compacting	( )					
Insufficient	operable	equipment on	site as requ	ired ( ) >	(2 ea. 2-8)			52
Uperational	roads unsa	tisfactory (	,	/				
		nuisance obse						53
Burning (4)	_, _, _, _	ot permitted	,=,			· · ·		54
Liquids ( ) So	olids() n	ot permitted	(5)	( ) (2	2.11			55
		ction( ) Site ) Sanitary Fa						
		or( ) Others(						
Salvaging Ob	served():	Improperly co	onducted in:	location(	)Operation(	)Storage(	)(1-3)	59
		served ( ) (						
Other (1-3)			RE					
, - <del>.</del> .			·	N. 44. * * * * * * * * * * * * * * * * *				
	<del></del>	<del></del>	OCT	07 1995		· <del></del>		
			•-	~ ~ ~ ~ ~				